

CONSUMER SAFETY NOTICE

[INVICTUS Speargun Handle Trigger mechanisms](#)

OMER as part of the Aqua Lung Group is conducting a voluntary product update of some INVICTUS SPEARGUN parts. INVICTUS triggers are found on OMER branded spearguns of the INVICTUS Family:

- INVICTUS REX, INVICTUS HF, INVICTUS CARBON

OMER / Aqua Lung is concerned that a failure may occur during a dive, causing the INVICTUS mechanism to block and as such, not release the shaft. While there have been reports of this occurring underwater, there have not been any reported injuries, but OMER / Aqua Lung believes that issuing a voluntary safety notice is the most safe and prudent thing to do.



INVICTUS spearguns without the mark "M" need to be serviced - **Requires an Update**

AQUALUNG GROUP
After sales service department
14ème Rue, 06513 Carros, France.



OMER



U.S.
DIVERS



AQUA LUNG
Military & Professional

AQUALUNG



Trigger mechanisms with the "M" have already been updated at the factory -
No further action required

Remedy: Consumers should immediately stop using their INVICTUS spearguns without the "M" marks on trigger and mechanisms.

Simply bring the Speargun to your nearest authorized OMER / Aqua Lung Dive Retailer or Dive Center. (Use our DEALER LOCATOR if you are not sure where your nearest dealer is: www.omersub.com/en/store-finder/)

They will be able to update your trigger mechanisms for you. The replacement is made under warranty and **you will not incur any charges.**

Consumer Contact - for additional assistance please visit Omersub.com and click on the [Consumer Safety Notices](#).

AQUALUNG GROUP
After sales service department
14ème Rue, 06513 Carros, France.

